

ATTENTION:

GENERAL MANAGER PARTS MANAGER
 CLAIMS PERSONNEL SERVICE MANAGER



SUBARU

IMPORTANT - All Service Personnel Should Read and Initial

SERVICE BULLETIN

APPLICABILITY: 2007MY B9 Tribeca, Legacy, & Forester **NUMBER:** 18-107-06
SUBJECT: Service Manual Corrections **DATE:** 07/17/06

INTRODUCTION

The purpose of this bulletin is to provide a description of current changes to Service Manuals available via the Subaru Technical Information System (STIS) web site. The tables contained within this bulletin are to be used as guides for becoming aware of the latest changes. We advise you to always refer to the STIS web site when looking for the latest Service information. Printed pages will not be made available to update printed Service Manuals.

YEAR	MODEL	MSA#	SECTION	PAGE	DESCRIPTION OF CHANGE
Paper manuals may have different page numbering then what is reflected below, based on multiple new and revised pages. Please refer to the information contained on the STIS web site for all future, update service manual information.					
2007	B9 Tribeca	MSA5T0741A	Engine	ME(H6DO)-20, 64, 70	Addition of ST 499057000 Torx Plus for removing the Drive Plate.
		MSA5T0744A	Body	AB(diag)-25	Connector chart updated.
				AB(diag)-35-36	Inspection steps changed.
				AB(diag)-42,45	Figures changed.
				AB(diag)-52,58,64,118,124	Wiring diagrams for DTC's 11, 15, 22, 71 & 75 have changed.
AB(diag)-72,81,83-84	Diagnostic steps changed for DTC's 26, 36, 38.				
2007	Legacy	MSA5T0700A	General Information	PM-9	Wording for Engine Oil filling has been modified.
		MSA5T0701A	Engine (H4SO)	GD(H4SO)-107, 109, 111, 113	Illustration changes for DTC's P0335, P0336, P0340, P0341.
		MSA5T0703A	Engine (H6DO)	ME(H6DO)-19, 60, 66	Addition of ST 499057000 Torx Plus for removing the Drive Plate.



CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.



YEAR	MODEL	MSA#	SECTION	PAGE	DESCRIPTION OF CHANGE
2007	Forester	MSA5T0721A	Engine (H4SO)	GD(H4SO)- 104, 106, 108, 110	Illustration changes for DTC's P0335, P0336, P0340, P0341.