

ATTENTION:
 GENERAL MANAGER PARTS MANAGER
 CLAIMS PERSONNEL SERVICE MANAGER
 IMPORTANT - All Service Personnel Should Read and Initial



SUBARU®

SERVICE BULLETIN

APPLICABILITY: 2007MY Forester Vehicles
SUBJECT: Service Manual Corrections

NUMBER: 18-113-06
DATE: 12/08/06

INTRODUCTION

The purpose of this bulletin is to provide a description of current changes to Service Manuals available via the Subaru Technical Information System (STIS) web site. The tables contained within this bulletin are to be used as guides for becoming aware of the latest changes. We advise you to always refer to the STIS web site when looking for the latest Service information. Printed pages will **not** be made available to update printed Service Manuals.

Paper manuals may have different page numbering then what is reflected below, based on multiple new and revised pages. Please refer to the information contained on the STIS web site for all future, updated service manual information.

YEAR	MODEL	BOOK/ VOL#	MSA#	SECTION	PAGE(S)	DESCRIPTION OF CHANGE
2007	Forester		MSA5T0720A	General Information	SPC-3, 5-10	Information for Sports model added.
					ID-5	Information for Sports model added.
			MSA5T0721A	Engine (H4SO)	EN(H4SO)(diag)-33	"LED OPERATION MODE OF ENGINE" and the contents are deleted.
					EN(H4SO)(diag)-75, 77, 103-104, 108-109, 111-112, 126, 128, 132, 141, 169, 171, 176-178, 182, 196, 198, 201, 203, 209-210, 216, 219, 221, 233, 255, 257, 259-260, 262, 268, 272, 295-296, 298, 314-316, 318, 320, 322, 324, 326, 328, 330-331, 334	Part or all of the diagnostic steps for the following DTCs have been modified: P0026, 28, 102, 107, 108, 0122, 123, 126, 134, 222, 223, 304, 328, 420, 442, 447, 452, 456, 457, 458, 464, 851(AT), 851(MT), 852(AT), 852(MT), 1400, 1443, 1602, 2101, 2102, 2103, 2122, 2123, 2127, 2128, 2135, 2138.
					EN(H4DOTC)(diag)-35	"LED OPERATION MODE OF ENGINE" and the contents are deleted.
			MSA5T0722A	Engine (DOTC)	EN(H4DOTC)(diag)-54	Step 4 under "INJECTOR COTROL" is modified.



CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

YEAR	MODEL	BOOK/ VOL#	MSA#	SECTION	PAGE(S)	DESCRIPTION OF CHANGE		
2007	Forester		MSA5T0722A	Engine (DOTC)	EN(H4DOTC)(diag)-98, 99-100, 104, 106, 120, 122, 126, 157, 159, 167, 177, 192, 209-211, 212, 215, 218, 224-225, 231, 234, 236, 270, 272, 274-275, 277, 283, 293, 307-310, 322-323, 327-328, 353-356, 358, 360, 362, 364, 366, 368, 370-372, 374-375, 377, 379	Part or all of the diagnostic steps for the following DTCs have been modified: P0102, 107, 108, 122, 123, 126, 222, 223, 245, 328, 411, 420, 441, 442, 447, 452, 456, 457, 458, 464, 851(AT), 851(MT), 852(AT), 852(MT), 1400, 1443, 1602, 2016, 2021, 2101, 2102, 2103, 2122, 2123, 2127, 2128, 2135, 2138, 2419, 2420.		
			MSA5T0723A	Transmission	4AT-3, 5, 12, 15, 17, 20, 26, 36-38, 41-45, 51, 53, 56, 101, 110, 113, 116, 120, 122	Many changes to the content on listed pages, review on STIS.		
							4AT(diag)-8, 12, 26, 27, 85-86	Information for Sports model added.
			MSA5T0724A	Chassis	VDC-1-32	VDC(diag)1-142	VDC section added.	
							VDC diagnostic section added.	
			MSA5T0726A	Wiring System		WI-18, 143	Illustration modified.	
							WI-20, 21, 23, 24, 25, 47, 60, 63, 67, 71, 75-78, 114, 137, 145, 146, 148, 149, 164, 165, 167, 168	Information for Sports model added.
							WI-10, 11, 16, 22, 27, 29-31, 34-44, 48-59, 64-66, 68-70, 72-74, 79, 81, 83-85, 88-101, 103, 105-108, 112, 116, 118, 119, 121, 133, 141, 147, 150, 151, 154, 157, 158	Pages modified to include Harness Repair information.
							WI-184-189	Harness Repair pages added.