



# SERVICE BULLETIN

**APPLICABILITY** 

1993-1997 All Models

DATE

12/01/96

**SUBJECT** 

Subaru Audio System Diagnosis, Identification and Exchange Procedures

This bulletin contains illustrations of Genuine Subaru Audio System face plates for model years 1993 through 1997.

#### SUBARU AUDIO DIAGNOSTIC REPORT

A copy of the Subaru Audio Diagnostic Report is printed on the last page of this Bulletin. It should be photocopied for use. The purpose of the Subaru Audio Diagnostic Report is to assist the Technician in the diagnosis of an audio system related complaint. The preliminary information, such as owner's name, vehicle VIN and the specific customer complaint should be completed by the Service Advisor. This will enable the Technician to check specific areas in order to isolate the cause. Note: Not all audio system complaints are related to the chassis, refer to Service Bulletin 15-91-91 for further Technical information.

A copy of the Subaru Audio Diagnostic Report should be completed and retained by the dealer for all audio system related warranty claims, Whether the audio unit is exchanged or not. If the audio chassis is exchanged, a completed report copy should be included with the return unit. If the audio chassis is not exchanged and a repair is made to the audio system, a completed report copy must be kept with the warranty claim.

#### **AUDIO EXCHANGE PROGRAM**

Within the terms of the Basic New Car Warranty, the Audio Exchange Program provides for replacement of a defective audio chassis with an exchange unit from the manufacturer. The manufacturer will supply an exchange unit, or a new unit in the case of a "New" and "In-stock" vehicle.

Genuine Subaru audio systems are manufactured by Clarion and Panasonic. In the event an audio chassis requires an exchange, it is not necessary to remove the unit from the vehicle. The procedures listed below should be followed:

- The defective chassis should remain in the vehicle until the exchange unit is installed.
- The manufacturer and model should be identified using the applicable Subaru Audio System Diagnosis, Identification and Exchange Procedures Warranty Bulletin.
- The applicable Service Center should be contacted. The Service Centers are open from 7 AM - 5 PM Pacific Time.

**CLARION** 

**PANASONIC** 

1-800-347-8933

1-800-228-0473

NOTE: In the event the vehicle is "New" and "In-stock", inform the Service Center. A new unit will be supplied rather than an exchange unit. If the Service Center is unable to provide a new unit, immediately contact your Subaru Service Representative for further instructions.

Vehicles that have been placed in demo service should use exchange units only.

Replacement of an audio chassis with a new unit, other than units supplied through the exchange program. requires authorization from your Subaru Service Representative. An authorized code will be provided and must be included upon claim submission.

- 4. Provide the Service Center with the following information:
  - Dealer Code
  - Dealer Name and Address
  - VIN All 17 Characters
  - Date of Vehicle Sale
  - Vehicle Mileage
  - Caller's Name and Telephone Number
  - Claim Number
  - Chassis Model Number, ID Code and/or the Subaru Part Number
  - Customer Complaint
  - Customer Last Name

At this time, the Service Center will issue an exchange number. It is required that this number be provided upon claim submission.

Panasonic Exchange Number Example ...... SP 00000001
Clarion Exchange Number Example ......FS 00000001

An exchange chassis along with an exchange form will be shipped within 72 hours. If the exchange chassis is not received within 5 days, call the Service Center. Provide the operator with the exchange number when making inquiries.


5. Install the exchange unit as soon as possible upon receipt.

Return the defective chassis to the manufacturer within 30 days. Return freight charges may be claimed as sublet, provided the repair was performed under the terms of the Basic New Car Warranty. Copies of the freight invoice should be attached to the repair order.

NOTE: If the exchange unit has not been installed or the failed chassis returned within 30 days, contact the Service Center. Reference the exchange number and explain the circumstances causing the delay. An extension will be granted or the dealer will be instructed to return the exchange unit. Failure to comply will result in a "charge back" to the dealer for the cost of the exchange unit.


OPERATION NUMBER	LABOR DESCRIPTIONS	l	OYALI	Ē		j U	LEG	ACY	IMPI	REZA	
		4 D R	S/W	3 D R	X T	S T Y	4 D R	S/W	4 D R	S/W	S V X
A 031-101	RADIO, CASSETTE, CD AND/OR EQUALIZER. (THIS OPERATION MAY BE CLAIMED ONE TIME ONLY FOR EXCHANGE PROGRAM.) R&R	0.3	0.3	0.3	0.3	0.4	0.3	0.3	0.3	0.3	0.4

#### **RADIO CHASSIS LEGACY**




40-WATT ETR WITHOUT AUXILIARY PLUG ID CODE ON FACE PLATE - C/P312 - C314

MODEL	VEHICLE	COMPONENT	MODEL NUMBER/
YEAR	APPLICATION	MANUFACTURER	PART NUMBER
'92- '96	LEGACY (C312 - C314)	CLARION	RF-9127A SOA333D166 H6200FS000
'91-	LEGACY	PANASONIC	CR-LF1011A
'93	(P312)		SOA416D161




80-WATT AM/FM CASSETTE COMBO UNIT ID CODE ON FACE PLATE - C/P 113

MODEL	VEHICLE	COMPONENT	MODEL NUMBER/
YEAR	APPLICATION	MANUFACTURER	PART NUMBER
'92-	LEGACY	CLARION	PF-9505IC
'94	(C/P 113)		SOA333DI72
		PANASONIC	CQ-LF1111Z SOA416D171




80-WATT AM/FM CASSETTE COMBO ID CODE ON FACE PLATE - P114

MODEL	VEHICLE APPLICATION	COMPONENT	MODEL NUMBER/
YEAR		MANUFACTURER	PART NUMBER
'95-	LEGACY	PANASONIC	CQ-LF1410A
'97	(P114)		86201AC070



80-WATT AM/FM CASSETTE COMBO WEATHER BAND RECEIVER ID CODE ON FACE PLATE - P115


MODEL	VEHICLE APPLICATION	COMPONENT	MODEL NUMBER/
YEAR		MANUFACTURER	PART NUMBER
<b>'97</b>	LEGACY (P115)	PANASONIC	CQ-LF1611Z 86201AC350



CD AUTO CHANGER
ID CODE ON FACE PLATE - P611


MODEL YEAR	VEHICLE APPLICATION	COMPONENT MANUFACTURER	MODEL NUMBER/ PART NUMBER
'95- '97	LEGACY CD CONTROLLER (P611)	PANASONIC	CY-CF1410F H6240AC520
	LEGACY CD CHANGER	PANASONIC	CX-CF1410F H6250AC510

## RADIO CHASSIS IMPREZA / SVX




40-WATT ETR WITHOUT AUXILIARY PLUG ID CODE ON FACE PLATE - C/P312 - C314

MODEL	VEHICLE	COMPONENT	MODEL NUMBER/
YEAR	APPLICATION	MANUFACTURER	Part Number
'93- '97	IMPREZA (C312 - C314)	CLARION	RF-9127A SOA333D166 H6200FS000




80-WATT AM/FM CASSETTE COMBO ID CODE ON FACE PLATE - C114, C115

MODEL	VEHICLE APPLICATION	COMPONENT	MODEL NUMBER/
Year		MANUFACTURER	Part Number
'93-	IMPREZA	CLARION	PF-9695AA
'94	(C114)		86201FA010
'95-	IMPREZA	CLARION	PF-9695A
'96	(C115)		86201FA170




80-WATT AM/FM CASSETTE COMBO ID CODE ON FACE PLATE - C116

MODEL	VEHICLE	COMPONENT	MODEL NUMBER/
YEAR	Application	MANUFACTURER	PART NUMBER
'97	IMPREZA (C116)	CLARION	PF-1509A 86201FA270




~~	ALITO	CHAR	CED

MODEL YEAR	VEHICLE Application	COMPONENT MANUFACTURER	MODEL NUMBER/ PART NUMBER
'93- '96	IMPREZA (4DR, SW) CD CONTROLLER	CLARION	EF-1027U-A H6240AC610
	IMPREZA (4DR, SW) CD CHANGER	CLARION	PS-2050U-B H6250AC600




ETR WITH CASSETTE COMBO UNIT ID CODE ON FACE PLATE - P411



CD PLAYER
ID CODE ON FACE PLATE - P511

MODEL YEAR	VEHICLE APPLICATION	COMPONENT MANUFACTURER	MODEL NUMBER/ PART NUMBER
'92- '97	SVX LS-L (P411)	PANASONIC	(6 SPEAKER) CQ-LF4011A 86201PA010
	SVX LS (P411)	PANASONIC	(4 SPEAKER) CQ-LF4012A 86201PA020
	SVX CD (P511)	PANASONIC	CX-DF4011A/F SOA416E150 86202PA000

# AUDIO ACCESSORIES LEGACY / IMPREZA




STANDARD CASSETTE DECK ID CODE ON FACE PLATE - 4130

MODEL	VEHICLE	COMPONENT	MODEL NUMBER/
YEAR	Application	MANUFACTURER	Part Number
'90-	LEGACY/IMPREZA	PANASONIC	CX-AF192 FUS
'95	(4130)		SOA416E130

TAPE DIRECTION	M SUBARU 3150 P T
	Trip UTL


FULL FEATURE CASSETTE DECK ID CODE ON FACE PLATE - 3150

MODEL	VEHICLE	COMPONENT	MODEL NUMBER/
YEAR	Application	Manufacturer	PART NUMBER
'90- '95	LEGACY/IMPREZA (3150)	CLARION	PF-8118U SOA333E150 H6220FS000




LOGIC CONTROL CASSETTE DECK ID CODE ON FACE PLATE - 3140

MODEL	VEHICLE	COMPONENT	MODEL NUMBER/
YEAR	Application	MANUFACTURER	PART NUMBER
'90-	LEGACY/IMPREZA	CLARION	PF-8119U
'94	(3140)		SOA333E140




COMPACT DISC PLAYER ID CODE ON FACE PLATE - 3160

MODEL	VEHICLE APPLICATION	COMPONENT	MODEL NUMBER/
YEAR		MANUFACTURER	Part Number
'90- '97	LEGACY (3160)	CLARION	PF-2016U SOA333E160 H6240FS000




COMPACT DISC PLAYER
ID CODE ON FACE PLATE - 3162, C611, C612

MODEL	VEHICLE	COMPONENT	MODEL NUMBER/
YEAR	APPLICATION	MANUFACTURER	Part Number
'92-	LEGACY/IMPREZA	CLARION	PF-2046
'97	(3162, C611, C612)		H6240FS000



COMPACT DISC PLAYER
ID CODE ON FACE PLATE - P512


MODEL	VEHICLE	COMPONENT	MODEL NUMBER/
YEAR	Application	Manufacturer	Part Number
'95-	LEGACY/IMPREZA	PANASONIC	CX-DF1410FC
'97	(P512)		H6240AS100



COMPACT DISC PLAYER
ID CODE ON FACE PLATE - NONE


MODEL	VEHICLE	COMPONENT	MODEL NUMBER/
YEAR	Application	MANUFACTURER	Part Number
'95- '97	LEGACY/IMPREZA	CLARION	PF-2100A-A H6240FS010

# RADIO CHASSIS LOYALE / JUSTY




10	IA/A	77	CTC

MODEL	VEHICLE	COMPONENT	MODEL NUMBER/
YEAR	Application	MANUFACTURER	PART NUMBER
'88-	LOYALE	CLARION	RF-9095I
'94	3DR, 4DR, SW		SOA333D117
		PANASONIC	CR-LF171A SOA416D117




MODEL	VEHICLE	COMPONENT	MODEL NUMBER/
Year	Application	MANUFACTURER	PART NUMBER
'89- '94	GL/RS JUSTY	PANASONIC	CR-LF581A S0A416D121



AM/FM CASSETTE COMBO ID CODE ON FACE PLATE - 3122


MODEL	VEHICLE	COMPONENT	MODEL NUMBER/
YEAR	Application	MANUFACTURER	Part Number
'89-	DL JUSTY	CLARION (KIT	SOA333D122
'94	(3122)	#SOA333D127)	

## CASSETTE DECKS LOYALE / JUSTY




	CLASSI	CC	ASSE	:77	ΈD	ECK	
in	CODEC	N I	FACE	Ρi	ATE	- 4	ſΛA

MODEL	VEHICLE	COMPONENT	MODEL NUMBER/	
YEAR	Application	MANUFACTURER	Part Number	
'89- '94	LOYALE JUSTY (4104)	PANASONIC	CX-AF186 FUS SOA416E104	
'90-	JUSTY	PANASONIC	CX-AF186 FUS	
'94	(4104)		SOA416E136	



PREMIUM CASSETTE DECK ID CODE ON FACE PLATE - 4115

MODEL	VEHICLE	COMPONENT	MODEL NUMBER/
YEAR	Application	MANUFACTURER	PART NUMBER
'89-	LOYALE	PANASONIC	CX-AF182 FUS
'94	(4115)		SOA416E115



E.Q. CASSETTE DECK

MODEL	VEHICLE APPLICATION	COMPONENT	MODEL NUMBER/	
YEAR		MANUFACTURER	PART NUMBER	
'88-	LOYALE	CLARION	PF8069U	
'94		(BLACK BUTTONS)	SOA333E131	
		CLARION (CHROME BUTTONS)	PF8069UC SOA333E130	

# SUBARU AUDIO DIAGNOSTIC REPORT

VIN	DEALER#
SUBARU CLAIM #	AUDIO MODEL#
DESCRIBE CUSTOMER COMPLAINT IN DETAIL:	

PROBLEM CO	NFIR	MED YES	NO		
	1	PROBLEM:	TECHNICIAN CHECK:		
GENERAL		INOP.	FUSE, LOOSE CONNECTION, WIRING	6 3 100	
AUDIO		FADES / CUTS OUT	SHORT TO CAR CHASSIS?		
			PINCHED WIRE		
		CHANNEL /SPEAKER OUT	PINCHED SPEAKER WIRE?		
			SHORT TO CAR CHASSIS?		
			LOOSE SCREW OR OTHER		
		POOR SOUND	FOREIGN OBJECT RUBBING SPEAKER		
			LOOSE CONNECTION		
		BALANCE / FADER	PROPER SETTING ?		
		BASS / TREBLE			
		ILLUMINATION	DASH RHEOSTAT SETTING		
			PINCHED WIRE, LOOSE CONNECTION		
		NOISE	PINCHED WIRE, LOOSE CONNECTION		
		(ALTERNATOR, ETC. )	ADD .5 MFD CAPACITOR		
			BETWEEN THE + LINE AND THE RADIO		
TUNER		POOR RECEPTION	ANTENNA OK ? COAX PINCHED ?		
			DISTANT STATION? BAD RCPT AREA?		
		MEMORY	PINCHED WIRE, LOOSE CONNECTION		
			CHECK FUSE		
CASSETTE		TANGLES TAPES	CHECK TAPE CONDITION		
			TIGHTEN TAPE REEL - IF LOOSE		
			DIRTY HEAD - USE CLEANER		
		WON'T EJECT TAPES	WARPED TAPE, PEELING LABELS		
		WON'T ACCEPT TAPES	FUSE		
		LOW / POOR SOUND	DIRTY HEAD - USE CLEANER		
			TEST USING KNOWN GOOD TAPE		
		TAPE SPEED	CHECK TAPE CONDITION		
			TIGHTEN TAPE REEL - IF LOOSE		
CD		SKIPS / EJECTS	CD UPSIDE DOWN? PINHOLES?		
			DIRTY OR SCRATCHED CD?		
			ROUGH ROAD CONDITIONS		

TECHNICIAN COMMENTS / FINDINGS (REQUIRED)

**TECHNICIAN SIGNATURE & DATE:** 

IF PROBLEM PERSISTS, ORDER REPLACEMENT UNIT. ENCLOSE THIS COMPLETED FORM WITH DEFECT UNIT.

FOR AUDIO MANU	FACTURER U	SE ONLY			
RECEIVED WITH D	HRTY HEADS		YES	NO	
PROBLEM CONFI	RMED		YES	NO	
TECHNICIAN					
FOR ADDITIONAL	COMMENTS L	SE REVERSE	SIDE		