

SERVICE BULLETIN

APPLICABILITY ALL '95/'96 MY LEGACY S/W INCLUDING
OUTBACK AND '96 MY IMPREZA ALL
MODELS INCLUDING OUTBACK

DATE 11-30-95

SUBJECT ACCESSORY PROTECTIVE BUMPER COVER ADHESION

If you encounter a customer complaint of the rear bumper protective cover peeling up on the left and/or right sides, use this procedure to re-attach the bumper cover to the bumperskin:

- Carefully lift up on the loose side, clean the bumperskin and the protective cover area to be re-attached using 3M General Purpose Adhesive Cleaner Part number 08984 or equivalent. Ensure both surfaces are clean and dry.
- Using ordinary masking tape, carefully mask-off around the edges of the bumperskin to prevent any adhesive spillage from damaging the bumperskin painted surface.
- Using 3M "Ultra-Pro" Trim and Emblem Adhesive part number 08063 or equivalent, apply the bonding adhesive to either the protective bumper cover or the bumperskin.
- Bond the protective cover to the bumperskin. Masking tape maybe used to secure the protective bumper cover in place until the adhesive dries. Immediately wipe-off any excess adhesive using 3M General Purpose Adhesive Cleaner part number 08984.

NOTE: The suggested products in this bulletin are manufactured and trade-marked by 3M. Always follow the manufacturers instructions when using their products.

This repair procedure can be claimed under the genuine Subaru Limited Warranty using the following information:

Failure Code	Operation #	Labor Description	Labor Time
Rear Bumper Protector ZAX - 06	A106 - 521	Rear Bumper Protector Repair	0.4 Hours

CAUTION

VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.