8. Inspection Mode S002510

A: OPERATION S002510A16

Recreate the circumstance by referring to the conditions described in the checklist.

AB-21

🖙 00.5.31/68j/0ab 🖘