9. Inspection Mode 5005510

A: OPERATION S005510A16

Reproduce the condition under which the problem has occurred as much as possible. Drive the vehicle at least ten minutes.

NOTE:

Make sure vehicle does not pull to one side during normal driving.