

2. Inspection Locations After a Collision SB01306

A: INSPECTION SB01306A10

Check for the following, and then replace with new parts if necessary.

- Center pillar lower garnish is discolored or cracked.
- Wire harness and/or connector is damaged.