3. Inspection Locations After a Collision

A: INSPECTION

Check for the following, and replace with new parts if necessary.

- Center piller lower trim is discolored or cracked.Wiring harness and connector are damaged.