


OP Connector System

WIRING SYSTEM

34.OP Connector System

A: WIRING DIAGRAM



OP-C-01

OP-C-01

B228

1	2		3
4	5	6	7
8	9	10	11
12	13	14	15

WI-09810