

ATTENTION:

- GENERAL MANAGER
- PARTS MANAGER
- CLAIMS PERSONNEL
- SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.



SUBARU[®]

QUALITY DRIVEN[®] SERVICE

SERVICE BULLETIN

APPLICABILITY: All Models
SUBJECT: Tire Rotation Pattern


NUMBER: 05-37-07
DATE: 03/12/07

INTRODUCTION


In an effort to further reduce uneven tire wear and prolong tire life, the tire rotation pattern has been changed for non-directional tires. To maximize the life of each tire and ensure that the tires wear uniformly, it is best to rotate the tires every 7,500 miles (12,000 km). Note: The tire rotation pattern for directional tires has not changed.

Reminder: When rotating tires on a vehicle equipped with TPMS (Tire Pressure Monitoring System) make sure to re-register the tires.


Tire Rotation Pattern for Non-Directional Tires



Tire Rotation Pattern for Directional Tires



Tire Rotation Branding



CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

