

1. Supplemental Restraint System "Airbag"

Airbag system wiring harness is routed near the transmission control module (TCM).

- 1. All Airbag system wiring harness and connectors are colored yellow. Do not use electrical test equipment on these circuit.**
- 2. Be careful not to damage Airbag system wiring harness when performing diagnostics and servicing the TCM.**

2. Precaution

1) Problems in the electronic-controlled automatic transmission may be caused by failure of the engine, the electronic control system, the transmission proper, or by a combination of these. These three causes must be distinguished clearly when performing diagnostics.

2) Diagnostics should be conducted by rotating with simple, easy operations and proceeding to complicated, difficult operations. The most important thing in diagnostics is to understand the customer's complaint, and distinguish between the three causes.