3. Inspection Locations After a Collision

A: INSPECTION

Check for the following, and then replace with new parts if necessary.

• Center pillar lower garnish is discolored or cracked.

• Wire harness and/or connector is damaged.