


54. Instrument Panel Wiring Harness

A: LOCATION

Connector				Connecting to	
No.	Pole	Color	Area	No.	Name
i1	24	Brown	B-3	B36	Bulkhead wiring harness
i2	24	★	B-3	B37	
i10	30	Green	B-2		Combination meter
i11	10	Green	B-3		
i12	14	Green	B-2		
i22	8	★	B-4		Hazard switch
i51	2	★	B-3		Sunload sensor
i59	4	★	B-3		Clock
★: Non-colored					

INSTRUMENT PANEL WIRING HARNESS

WIRING SYSTEM



WI-02522