

## 10. Inspection Mode S005510

### A: OPERATION S005510A16

Reproduce the condition under which the problem has occurred as much as possible.  
Drive the vehicle at least ten minutes.

#### NOTE:

Make sure vehicle does not pull to one side during normal driving.