


9. Theft Prevention


The Theft Prevention (T.P.) label is stuck or V.I.N. is inscribed on the main line installed parts shown below. Additionally, the "R DOT" label is stuck or "R DOT" is inscribed on the main spare parts shown below.

A: T.P. LABEL AND "R DOT" LABEL



B: LOCATION

1. INSCRIPTION



GENERAL INFORMATION

2. LABEL

