

INSPECTION LOCATIONS AFTER A COLLISION

SEAT BELT SYSTEM

3. Inspection Locations After a Collision

A: INSPECTION

Check for the following, and then replace with new parts if necessary.

- Center pillar lower garnish is discolored or cracked.
- Wiring harness and/or connector is damaged.