

---

## 7. Rear Tone Wheel S401182

### A: REMOVAL S401182A18

Refer to Rear Drive Shaft, because rear tone wheel is integrated with rear drive shaft.

<Ref. to DS-33 REMOVAL, Rear Drive Shaft.>

### B: INSTALLATION S401182A11

Refer to Rear Drive Shaft, because rear tone wheel is integrated with rear drive shaft.

<Ref. to DS-33 INSTALLATION, Rear Drive Shaft.>

### C: INSPECTION S401182A10

Visually check tone wheels teeth (44 pieces) for cracks or dents. If necessary, replace tone wheel with a new one.

#### NOTE:

Replace BJ assembly with new one as a single unit if there are any defects found on tone wheel is unitized with BJ assembly of drive shaft.