

3. Rear Window Defogger System S905455

A: SCHEMATIC S905455A21

<Ref. to WI-143, Rear Window Defogger System.>

REAR WINDOW DEFOGGER SYSTEM

Glass/Windows/Mirrors

B: INSPECTION S905455A10

Symptom	Repair order
Rear window defogger does not operate.	(1) Fuse (M/B No. 1) (2) Rear defogger relay (3) Defogger switch (4) Rear defogger condenser (5) Deffogger wire (6) Wire harness