

5. Remote Control Mirror System S905458

A: SCHEMATIC S905458A21

<Ref. to WI-144, Remote Controlled Rearview Mirror System.>

REMOTE CONTROL MIRROR SYSTEM

Glass/Windows/Mirrors

B: INSPECTION S905458A10

Symptom	Repair order
All functions do not operate.	(1) Fuse (F/B No. 4) (2) Mirror switch (3) Wire harness
One side of the mirror motor does not operate.	(1) Mirror switch (2) Mirror motor (3) Wire harness
Mirror heater does not operate.	(1) Mirror switch (2) Mirror heater (3) Wire harness