# 21.Rear Side Marker Light Bulb


# A: REMOVAL

## 1. SEDAN MODEL

A bulb is not equipped on the sedan model, since it is a reflex reflector type.

#### 2. WAGON MODEL

- 1) Remove the rear combination light assembly. <Ref. to LI-21, WAGON MODEL, REMOVAL, Rear Combination Light Assembly.>
- 2) Turn the socket and remove the bulb.



## **B: INSTALLATION**

Install in the reverse order of removal.

## C: INSPECTION

- 1) Visually check the bulb for blow out.
- 2) Check the bulb specification.
- <Ref. to LI-2, SPECIFICATION, General Description.>
- 3) If NG, replace the bulb with a new part.